

NOZZLES

Air Consumption Table

The table below shows the volume of compressed air required to tun a pressure blast system efficiently.

Pressure	Cubic Feet per Minute at: (p.s.i.)					
Nozzle	50	60	70	80	90	100
1/8" (3mm)	11	13	15	17	18	20
3/16" (5mm)	26	30	33	38	41	45
1/4" (6.5mm)	47	54	61	68	74	81
5/16" (8mm)	77	89	101	113	126	137
3/8" (9.5mm)	108	126	143	161	173	196
7/16" (11mm)	147	170	194	217	240	264
1/2" (12.5mm)	195	224	252	280	307	338